

**Mbsm.pro, compressor, Gree,
Air conditioner, 0XSH-
F375E090, 0XSH-F375, 22100
BTU, 37.50 cm³, 6477 w,
capacitor 60 uf, 1.8 ton, 2.8
hp, 220 v, 1ph, r22**

written by Lilianne | 28 January 2024

 **GREE**

QXSH-F375E090

1PH 50Hz


220-240V~

R22



LD887BZ31100094

ZHUHAI LANDA COMPRESSOR CO., LTD.



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, compressor, Gree, Air conditioner, OXSH-F375E090, OXSH-F375, 22100 btu, 37.50 cm³, 6477 w, capasitor 60 uf, 1.8 ton, 2.8 hp, 220 v, 1ph

Mbsm.pro, Solutions, F0, Code, F0 Error, Gree, Mini Split, Air Conditioner

written by Lilianne | 28 January 2024



Mbsm.pro, Solutions, F0, Code, F0 Error, Gree, Mini Split, Air Conditioner

**Mbsm.pro, Compressor, Gree,
Rotary Compressors, QXSH-
F42E030, 24000 BTU/HR, 2 ton,
3 Hp, 1PH / 220 v, r22**

written by Lilianne | 28 January 2024



Private Picture Copyright: WWW.MBSM.PRO

Mbsm.pro, Compressor, Gree, Rotary Compressors, QXSH-F42E030,
24000 BTU/HR, 2 ton, 3 Hp, 1PH / 220 v, r22

**Mbsm.pro, GREE, Air
Conditioners, VRF-system,
GMV-615WM/G-X, inverter, 22
hp, 615000 btu/h, 61.5 kw,**

Cooling / heating, r410a, dc motor, multi-speed, T3, 380-415V 3N~50/60Hz

written by Lilianne | 28 January 2024



Private Picture Copyright: WWW.MBSM.PRO

Mbsm.pro, GREE, VRF-system, GMV-615WM/G-X, inverter, 22 hp, 615000 btu/h, 61.5 kw, Cooling / heating, r410a, dc motor, multi-speed, T3

**Mbsm.pro, Gree, air
conditioner,
GWHD(14)NK6L0(LC)(LH),
GWHD(14)NK6L0, CB228W08401,
CB228W08400, 14000 btu,
Inverter Rotary, Compressor,
QXA-B141zF030A, 2 hp-, 1440
w, lra 25 A, DC block
controller, r410a, 220 v, 50
hz, 900 to 7200 RPM**

written by Lilianne | 28 January 2024

TOSOT

QXA-B141zF030E

260-350V 900-7200rpm R410A



LDB42DA428H0503

ZHUHAI LANDA COMPRESSOR CO., LTD.

Mbsm.pro, Gree, air conditioner, GWHD(14)NK6L0(LC)(LH), GWHD(14)NK6L0, CB228W08401, CB228W08400, 14000 btu, Inverter Rotary, Compressor, QXA-B141zF030A, 2 hp-, 1440 w, Ira 25 A, DC block controller, r410a, 220 v, 50 hz, 900 to 7200 RPM

www.mbsm.pro, GREE , Mini Split , Air Conditioner ,Error Codes E6 , How To Fix

written by Jamila | 28 January 2024

The error E6 comes from the engine, it is the electronic engine card if it is an inverter range.

Communication error E6 Between Outside and inside

www.mbsm.pro, Branchement Unité extérieure , LG ,Media , Général , Samsung, Haier , Galanze ,Gree ,Maxwelle, Vestel

written by Jamila | 28 January 2024

Branchement Unité extérieure , LG ,Media , Général , Samsung, Haier , Galanze ,Gree ,Maxwelle, Vestel