

# Mbsm.pro, COMPRESOR, TECUMSEH, BRASIL, 1/5 HP, TW1368YS, R-134, 1bp

Category: compressor

written by Lilianne | 12 January 2024



HP	Compresor	ERR Btu/Wh
1/8	THG1340YS	4,25
1/6	THG1352YS	4,40
1/5	THG1358YS	4,41
1/5+	TW1368YS	4,26
	TSA1374YS	4,90
1/4	TW1380YS	4,45
	TSA1380YS	5,10
	TPH1380YS	5,00





R134a 11.6 12.3  
220V 50 Hz  
TW 140 - GS  
TW 1368YS  
52 89417 100  
HERSHELTY

**▲ WARNING** To avoid burns, immediately get away if you hear sizzling or popping inside the compressor. Improper servicing can lead to explosions. Service only by trained professional.

**▲ ADVERTENCIA** Para evitar quemaduras, RETÍRESE INMEDIATAMENTE si oír chisporroteo o popping instalados dentro del compresor. El mantenimiento inadecuado puede causar electrocución, incendio o explosión. Solo servicio profesional autorizado. Nunca hacer los arreglos de mantenimiento.

**▲ ATENÇÃO** Para evitar queimaduras, RETIRE-SE Imediatamente se ouvir sons de chiapisco ou popocamento dentro do compressor. Manutenção inadequada pode levar a eletrocussão, incêndio ou explosão. Somente profissionais treinados realizem o serviço. Nunca realize o serviço de



HP	Compresor	ERR Btu/Wh
1/8	THG1340YS	4,25
1/6	THG1352YS	4,40
1/5	THG1358YS	4,41
1/5+	TW1368YS	4,26
	TSA1374YS	4,90
1/4	TW1380YS	4,45
	TSA1380YS	5,10
	TPH1380YS	5,00

