

**Mbsm.pro, Compressor,
Danfoss, Secop, 5/8 hp++,
SC21MFX, MBP, R134a, 220
V-240 V, 50 Hz, 104G8120,
8120**

written by Lilianne | 17 February 2022



Private Picture Copyright: WWW.MBSM.PRO

Mbsm.pro, Compressor, Danfoss, Secop, 5/8 hp++, SC21MFX, MBP, R134a, 220 V-240 V, 50 Hz, 104G8120, 8120

**Mbsm.pro, COMPRESSOR,
TECUMSEH, AE4470E, AE-8155-
br, 3/4 hp++, 1/2 Hp-, 220V,
1 PH, R22, M-HBP, ++(big)**

written by Lilianne | 17 February 2022



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, COMPRESSOR, TECUMSEH, AE4470E, AE-8155-br, 3/4 hp++,
1/2 Hp-, 220V, 1 PH, R22, M-HBP, ++(big)

Mbsm.pro, Compressor, TLS6F, Danfoss, 102G4620, Lbp, 125 W, 220 v, 1/6 Hp, 1 phase, R134a

written by Lilianne | 17 February 2022



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Compressor, TLS6F, Danfoss, 102G4620, Lbp, 125 W, 220 v, 1/6 Hp, 1 phase, R134a

**Mbsm.pro, Compressor, 1/3 hp,
tecumseh, r12, Se309-12,
AEA1410AXA (1/4 Hp ++), lbp,
1.47 A fla, Whirlpool
ET8WTKXK (18 FEET), Top
Freezer Refrigerator, 220 v**

written by Lilianne | 17 February 2022



Mbsm.pro, Compressor, 1/3 hp, tecumseh, r12, Se309-12,
AEA1410AXA (1/4 Hp ++), lbp, 1.47 A fla, Whirlpool ET8WTKXK
(18 FEET), Top Freezer Refrigerator

**Mbsm.pro, Compressor,
tw1390ys, tw160-ms-472,
Tecumseh, TW160KS, r134a,
Ariston, Indesit, lbp, 1/3
hp, 220 v**

written by Lilianne | 17 February 2022



8114b LRA-19.9
220 - 230V ~ 60 Hz
200 - 220V ~ 50 Hz

TW160 - MS - 472
TW1390YS

CE COUNTRY OF ORIGIN: BRAZIL THERMALLY PROTECTED

WARNING **ADVERTENCIA**

IMMEDIATELY GET AWAY
If you hear sizzling,
smoking or popping inside
the transformer, stop
working and leave the
area immediately. Do not
touch the transformer or
any other equipment in the
area.

RETIROSE IMEDIATAMENTE
Se ouvir zumbido,
fumaça dentro do transformador,
ou ruídos dentro do transformador,
pare imediatamente de trabalhar,
saia imediatamente da área e não
toque no transformador ou qualquer
outro equipamento na área.

Mbsm.pro, Compressor, tw1390ys, tw160-ms-472, Tecumseh, TW160KS
, r134a, Ariston, Indesit, lbp, 1/3 hp,

**Mbsm.pro, compressor,
refrigerator, NTH115MT, Turk
Elektrik, 115 Kcal/h, 1/5 hp,
TEE compressor, r600a, lbp,
BEKO Fridge Freezer
Compressor, 220 v**

written by Lilianne | 17 February 2022



 HERMETIC COMPRESSOR
NTH 115 MT H309-05

 SUCTION ← 230VAC 50Hz
 LRA:8.1 LBP R-600a S
 11190081 ZV19 12:04
   

H309-05
 11190081 ZV19
 12:04

Mbsm.pro, compressor, refrigerator, NTH115MT, Turk Elektrik, 115 Kcal/h, 1/5 hp, TEE compressor, r600a, lbp, BEKO Fridge Freezer Compressor, 220 v

Mbsm.pro, Compressor, Turk Elektrik, AZ 90 YT, TEE compressor, R134a, 90 Kcal/h, refrigerator with 240 liter, lbp , 220 v

written by Lilianne | 17 February 2022



TCC TÜRK ELEKTRİK
AZ 90 YT
230VAC 0Hz
KUSTON Z 31
LRA-11.0 LRP N° 340 S
0566175 RM09 20:35
[TCC] CE

Mbsm.pro, Compressor, Turk Elektrik, AZ 90 YT, TEE compressor, R134a, 90 Kcal/h, refrigerator with 240 liter, lbp , 220 v

**Mbsm.pro, Compressor,
TW1374ys, Tw145-ks-482, 1/4
hp, lbp, 195 w, 220 v, 1 ph,
TECUMSEH, INDESIT, R134**

written by Lilianne | 17 February 2022



Mbsm.pro, Compressor, TW1374ys, Tw145-ks-482, 1/4 hp, lbp, 195
w, 220 v, 1 ph, TECUMSEH, INDESIT, R134

**Mbsm.pro, Compressor, 1/7 HP
, THG1352YKS, th221-ks-324,
Tecumseh, LBP, R134a,
220-240V ~ 50Hz, 1 PH**

written by Lilianne | 17 February 2022



TH221-KS-324
THG1352YKS
R134a LRA 9.0
220-240V ~ 50 Hz
CE
C
51 01106 31 001104
COUNTRY OF ORIGIN: BRAZIL THERMALLY PROTECTED

▲ WARNING
To avoid burns, IMMEDIATELY GET AWAY if you hear sizzling, sputtering or popping inside the compressor. Improper servicing can lead to electrocution, fire or explosion. Service only by trained professional.

▲ ADVERTENCIA
Para evitar quemaduras, RETÍRESE INMEDIATAMENTE si oír chisporroteo, siseos o estallidos dentro del compresor. El mantenimiento inadecuado puede causar electrocución, incendio o explosión. Soloamente profesionales certificados pueden hacer los servicios de mantenimiento.

▲ ATENÇÃO
Para evitar queimaduras, RETIRE-SE IMEDIATAMENTE se ouvir sons de crepitação, sibilos ou pipocamento dentro do compressor. Manutenção inadequada pode levar à electrocussão, queimado ou explosão. Somente profissionais treinados poderão realizar serviços de manutenção.

Mbsm.pro, Compressor, 1/7 HP , THG1352YKS, th221-ks-324,
Tecumseh, LBP, R134a, 220-240V ~ 50Hz, 1 PH

Mbsm.pro, Compressor, Tecumseh, THB1350YS, R-134a 1/5HP, 230V, lbp

written by Lilianne | 17 February 2022



Mbsm.pro, Compressor, Tecumseh, THB1350YS, R-134a 1/5HP, 230V,
lbp