

COMPRESOR, 1/2+ HP, 6.639 BTU/h,
R-134a, 220V, PH1, CSR, HBP, CUBIGEL,
GPT16RG

Category: compressor

written by Amina | 31 October 2023



COMPRESOR, 1/2+ HP, 6.639 BTU/h, R-134a, 220V, PH1, CSR, HBP, CUBIGEL, GPT16RG

TFS4AT, 102u 2081, 102u2081, 1/12 hp,
r12, Lbp, 80 w / -25 °C, -10/-40 °C,
Danfoss, r12, r22, r502, Compressor,
PDF

Category: compressor,Files

written by Amina | 31 October 2023



TFS4AT, 102u 2081, 102u2081, 1/12 hp, r12, Lbp, 80 w / -25 °C, -10/-40 °C,
Danfoss, r12, r22, r502, Compressor, PDF

Original, R600A, Jiaxipera, Fridge,
compressor, T1114Y, 1/5 hp, 168 W,
lbp, 9.6 cm³

Category: compressor

written by Amina | 31 October 2023

jiaxipera®

CCC (C) (S) (M) CE

Warning Risk of fire / Flammable materials
JIAXIPERA COMPRESSOR CO., LTD

TG1114Y

220-240V-50Hz

R600a

AL

SUCTION

TG1114YP112905843

Original, R600A, Jiaxipera, Fridge, compressor, T1114Y, 1/5 hp, 168 W, lbp

Compressor, TLS4FT, SECOP, 102G4424,
102G 4424, DANFOSS, 1/8 hp++, 98 w,
lbp, r134

Category: compressor

written by Amina | 31 October 2023



Private Picture Copyright : WWW.MBSM.PRO

Compressor, TLS4FT, SECOP, 102G4424, 102G 4424, DANFOSS, 1/8 hp++, 98 w, lbp, r134

Compressor, Samsung, MSA182Q-L2H, 1/3 hp, Lbp, 264 Kcal, 307 W, 1048 Btu, r134a, refrigerator, RT72SBPN, 1.3 A, 554 L, 2 Doors

Category: compressor

written by Amina | 31 October 2023



Private Picture Copyright : WWW.MBSM.PRO

Compressor, Samsung, MSA182Q-L2H, 1/3 hp, Lbp, 264 Kcal, 307 W, 1048 Btu, r134a, refrigerator, RT72SBPN, 1.3 A, 554 L, 2 Doors

Commercial refrigerator, compressors, GLY16RG, 3/8 hp++, R134a, HMBP, 1492W, r134, Compressor ACC, Cubigel, Huayi, Electrolux, ZEM

Category: compressor

written by Amina | 31 October 2023



Private Picture Copyright : WWW.MBSM.PRO

Commercial refrigerator, compressors, GLY16RG, 3/8 hp++, R134a, HMBP, 1492W,

r134, Compressor ACC, Cubigel, Huayi, Electrolux, ZEM

Compressor, hermetic, piston, Embraco, NEK6214U, 1/2 hp++, hbp, R290, 12,12 cm³

Category: compressor

written by Amina | 31 October 2023



Private Picture Copyright : WWW.MBSM.PRO

Compressor, hermetic, piston, Embraco, NEK6214U, 1/2 hp++, hbp, R290, 12,12 cm³

PANASONIC, A/C, Compressor, 2KS324D5LA04, 18000 BTU, r22, 1.5 ton, K Series

Category: compressor

written by Amina | 31 October 2023



Private Picture Copyright : WWW.MBSM.PRO

PANASONIC, A/C, Compressor, 2KS324D5LA04, 18000 BTU, r22, 1.5 ton, K Series

RT 1320 windsor, windsor refrigerator, 13.2 Feet/cub, 400 L, Compressor, Embraco, ecu75hlp, 250 w, 1/4 hp, Lbp, r134, 180 g, 7.5 cm³, 220-240 V at 50 Hz

Category: compressor

written by Amina | 31 October 2023



RT 1320 windsor, windsor refrigerator, 13.2 Feet/cub, 400 L, Compressor, Embraco, ecu75hlp, 250 w, 1/4 hp, Lbp, r134, 180 g, 7.5 cm³, 220-240 V at 50 Hz

Tecumseh, AEZ1410D, compressor, 1/3 HP, r12

Category: compressor

written by Amina | 31 October 2023

R12 LRA 14.6

208-220V ~ 50Hz RLA 1.6

6A36490300
AEZ1410D

CE

52 D1405 10 143826 A

COUNTRY OF ORIGIN: FRANCE THERMALLY PROTECTED

⚠ WARNING **⚠ ADVERTENCIA** **⚠ AVERTISSEMENT**

To avoid burns,
IMMEDIATELY GET AWAY
if you hear sizzling,
whistling or popping inside
the compressor.
Improper servicing can lead
to electrocution, fire or
explosion. Service only by
trained professionals.

Para evitar quemaduras,
RETIRESE INMEDIATAMENTE
al oír chisporroteos, siseos o
estallidos dentro del compresor.
El mantenimiento inadecuado
puede causar electrocución,
incendio o explosión. Solamente
profesionales entrenados
pueden hacer los servicios de
mantenimientos.

Pour vous prévenir de brûlures,
ELOIGNEZ VOUS IMMEDIATEMENT
si vous entendez des crépitements,
crépitements ou petites explosions à
l'intérieur du compresseur.
Une maintenance inappropriée
peut engendrer un incendie, une
électrocution ou une explosion.
Toute intervention est réservée à
un professionnel habilité.

Private Picture Copyright : WWW.MBSM.PRO

Tecumseh, AEZ1410D, compressor, 1/3 HP, r12