

**Mbsm.pro, Compressor, 1/3 hp,
tecumseh, r12, Se309-12,
AEA1410AXA (1/4 Hp ++), lbp,
1.47 A fla, Whirlpool
ET8WTKXK (18 FEET), Top
Freezer Refrigerator, 220 v**

written by Lilianne | 16 February 2022



Mbsm.pro, Compressor, 1/3 hp, tecumseh, r12, Se309-12,
AEA1410AXA (1/4 Hp ++), lbp, 1.47 A fla, Whirlpool ET8WTKXX
(18 FEET), Top Freezer Refrigerator

**Mbsm.pro, Compressor,
tw1390ys, tw160-ms-472,
Tecumseh, TW160KS, r134a,
Ariston, Indesit, lbp, 1/3
hp, 220 v**

written by Lilianne | 16 February 2022



Mbsm.pro, Compressor, tw1390ys, tw160-ms-472, Tecumseh, TW160KS
, r134a, Ariston, Indesit, lbp, 1/3 hp,

**Mbsm.pro, compressor,
refrigerator, NTH115MT, Turk
Elektrik, 115 Kcal/h, 1/5 hp,
TEE compressor, r600a, lbp,
BEKO Fridge Freezer
Compressor, 220 v**

written by Lilianne | 16 February 2022



TEE HERMETIC COMPRESSOR
NTH 115 MT H309-05
[Barcode]
SUCTION 230VAC 50Hz
LRA:8.1 LBP R-600a S
11190081 ZV19 12:04
RoHS



NTH 115 MT H309-05
11190081 ZV19 12:04

Mbsm.pro, compressor, refrigerator, NTH115MT, Turk Elektrik, 115 Kcal/h, 1/5 hp, TEE compressor, r600a, lbp, BEKO Fridge Freezer Compressor, 220 v

Mbsm.pro, Compressor, Turk Elektrik, AZ 90 YT, TEE compressor, R134a, 90 Kcal/h, refrigerator with 240 liter, lbp , 220 v

written by Lilianne | 16 February 2022



TCC TÜRK ELEKTRİK
AZ 90 YT
230VAC 0/12
SÜTİYON Z 31
LRA-11.0 LRP N° 340 B
0566175 RM09 20:35
[TCC] CE

Mbsm.pro, Compressor, Turk Elektrik, AZ 90 YT, TEE compressor, R134a, 90 Kcal/h, refrigerator with 240 liter, lbp , 220 v

**Mbsm.pro, Compressor,
TW1374ys, Tw145-ks-482, 1/4
hp, lbp, 195 w, 220 v, 1 ph,
TECUMSEH, INDESIT, R134**

written by Lilianne | 16 February 2022



Mbsm.pro, Compressor, TW1374ys, Tw145-ks-482, 1/4 hp, lbp, 195
w, 220 v, 1 ph, TECUMSEH, INDESIT, R134

**Mbsm.pro, Compressor, 1/7 HP
, THG1352YKS, th221-ks-324,
Tecumseh, LBP, R134a,
220-240V ~ 50Hz, 1 PH**

written by Lilianne | 16 February 2022



TH221-KS-324
THG1352YKS
R134a LRA 9.0
220-240V ~ 50 Hz
CE
C
51 01106 31 001104
COUNTRY OF ORIGIN: BRAZIL THERMALLY PROTECTED

▲ WARNING
To avoid burns, IMMEDIATELY GET AWAY if you hear sizzling, sputtering or popping inside the compressor. Improper servicing can lead to electrocution, fire or explosion. Service only by trained professional.

▲ ADVERTENCIA
Para evitar quemaduras, RETÍRESE INMEDIATAMENTE si oír chisporroteo, siseos o estallidos dentro del compresor. El mantenimiento inadecuado puede causar electrocución, incendio o explosión. Soloamente profesionales certificados pueden hacer los servicios de mantenimiento.

▲ ATENÇÃO
Para evitar queimaduras, RETIRE-SE IMEDIATAMENTE se ouvir sons de crepitação, sibilos ou pipocamento dentro do compressor. Manutenção inadequada pode levar à electrocussão, queimadura ou explosão. Somente profissionais treinados poderão realizar serviços de manutenção.

Mbsm.pro, Compressor, 1/7 HP , THG1352YKS, th221-ks-324,
Tecumseh, LBP, R134a, 220-240V ~ 50Hz, 1 PH

**Mbsm.pro, Compressor,
Tecumseh, THB1350YS, R-134a
1/5HP, 230V, lbp**

written by Lilianne | 16 February 2022



Mbsm.pro, Compressor, Tecumseh, THB1350YS, R-134a 1/5HP, 230V,
lbp

**Mbsm.pro, Compressor,
Huaguang , EKA95, LBP, R-600,
165 W, CHINA, 1/5 Hp**

written by Lilianne | 16 February 2022



Mbsm.pro, Compressor, Huaguang , LBP, R-600, 165 W, CHINA, 1/5
Hp,

Mbsm.pro, Cubigel, Compressor, GPY14R, R134a, HMBP, 3/8 HP, HMBP, 14.32cc, High Efficiency

written by Lilianne | 16 February 2022



Mbsm.pro, Cubigel, Compressor, GPY14R, R134a, HMBP, 3/8 HP,
HMBP, 14.32cc, High Efficiency,

Mbsm.pro, Compressor, 7/8 HP, R404A, Secop, Commercial Freezer, Sc21cl, 104L2322, Sc21cl104L2322, 104L2322, 104L 2322, LBP, 2322

written by Lilianne | 16 February 2022



Private Picture Copyright: WWW.MBSM.PRO

Mbsm.pro, Compressor, 7/8 HP, R404A, Secop ,Commercial Freezer, Sc21cl, 104L2322, Sc21cl104L2322, 104L2322, 104L 2322, LBP