

# R134a, FL1568-SL, HITACHI Compressor, 220 v 50Hz, 1/4 Hp, white whale, 18Feet, LBp, 200W

written by Lilianne | 26 May 2020

Mbsm\_dot\_pro\_private\_PDF\_P\_COM008\_105\_specTélécharger

14/8/2556

OVERLOAD RELAY - Hitachi Compressor (Thailand) ,Ltd..htm

FL0739-S*	3.9	94	81	321	270	St		RSIR	7.8	179	
FL0845-S*	4.5	117	100	400	270	St		RSIR	8.1	179	
FL1052-S*	5.2	121	104	413	270	St		RSIR	8.3	179	
FL1152-S*	5.2	136	117	464	260	St		RSCR	8.3	179	
FL1152-S*	5.2	134	115	457	280	St		RSIR	9.3	188	
220-240V 50Hz FL1157-S*	5.7	136	117	464	240	St		RSIR	8.7	178	
FL1257-S*	5.7	150	129	512	240	St		RSIR	9.3	181	
FL1257-S*	5.7	173	148	591	240	St		RSCR	9.3	181	
FL1262-S*	6.2	145	124	495	310	St		RSIR	10.5	200	
FL1462-S*	6.2	165	142	563	310	St		RSIR	10.5	200	
FL1462-S*	6.2	185	159	632	310	St		RSCR	11.9	216	
FL1568-S*	6.8	180	154	615	310	St		CSIR	11.5	216	
FL1568-S*	6.8	200	172	683	310	St		RSIR	10.5	200	
FL1568-S*	6.8	200	172	683	310	St		RSCR	10.5	200	
FL1875-S*	7.5	215	184	734	335		OC	RSIR	10.8	211	
FL1875-S*	7.5	208	178	710	310			F	RSIR	11.9	216
FL1888-S*	8.8	207	178	707	300		OC	RSIR	11.2	216	
FL2088-S*	8.8	256	220	874	380			F	CSR	11.4	210
FL2088-S*	8.8	245	210	836	300		OC	RSCR	11.9	216	
FL2088-S*	8.8	245	210	836	300		OC	CSIR	11.9	216	
FL2088-S*	8.8	245	210	836	300		OC	RSIR	11.6	216	






Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

HITACHI FL1568-SL

220-240V 50Hz **OIL** 2008.09.26



SERIAL NO. 22692 HFC-134a

 WARNING: HIGH TEMPERATURE  
ELECTRIC SHOCK

DO NOT TOUCH M15

Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

