

# Compressor, FLB075LBNA, LG-Original New Linear Refrigerator Compressor, LG-compressor, Inverter 0~220V 53Hz, R134a(165g), LSXC22386, LSXC22326, LSXC22336, 1/4HP

written by Lilianne | 17 October 2021

FLS075LANA is the new **compressor** model number It replaces these older **LG/Kenmore Elite compressor** versions: FC75LBNA  
FLA075LANA FLB075LANA **FLB075LBNA**

Compressor Fls075lana\_replacement A: Fla075lana, Flb075lana

Compressor, FLB075LBNA, LG-Original New Linear Refrigerator Compressor, LG-compressor, Inverter 0~220V 53Hz, R134a(165g), LSXC22386, LSXC22326, LSXC22336, 1/4HP

New version LG Compressor part # TCA38091801 & Software Jig TCA35911910

Compressor has a purple decal and red decal on top warning about the software update.

FLS075LANA is the new compressor model number

It replaces these older LG/Kenmore Elite compressor versions:

FC75LBNA

FLA075LANA

FLB075LANA

FLB075LBNA







SEARS BRANDS  
MANAGEMENT CORPORATION  
HOFFMAN ESTATES, IL 60179

HOUSEHOLD REFRIGERATOR/  
REFRIGÉRATEUR MENAGERE

**MODEL/MODÈLE :**  **795.73153.610**

RATING/CAPACITÉ NOMINALE 115V ~ 60Hz 2.9A

REFRIGERANT/RÉFRIGÉRANT R134a 5.11oz

DEFROSTING INPUT / PUISSANCE ABSORBÉE EN DÉGIVRAGE 360W

POWER INPUT OF DEFROST HEATER /

PUISSANCE ABSORBÉE DE LA RÉSISTANCE DE DÉGIVRAGE 350W

FREEZER/CONGÉLATEUR 350W

PRODUCTION DATE / DATE DE PRODUCTION 2016.04

DIMENSIONS 35 3/4(W) x 36 1/4(D) x 70 1/4(H) inch

DESIGN PRESSURES/ HIGH SIDE/ CÔTÉ SUPÉRIEUR 400PSI Ga

PRESSION DE DESSIN LOW SIDE/ CÔTÉ INFÉRIEUR 140PSI Ga

SER.No./NO.DE SÉRIE:

MADE IN KOREA  
FABRIQUÉ EN CORÉE



**604KR00971**



For SEARS REPAIR SERVICE  
CALL 1-844-553-6667  
AU CANADA POUR SERVICE EN  
FRANÇAIS 1-800-LE-FOYER<sup>SM</sup>  
24HOURS A DAY,  
7 DAYS A WEEK FOR SEARS  
REPAIR SERVICE  
LE SERVICE DE REPARATION  
SEARS CANADA  
VINGT-QUATRE HEURES PAR JOUR,  
SEPT JOURS PAR SEMAINE.

TAB37097603 

