

www.mbsm.pro, GREE , Mini Split , Air Conditioner ,Error Codes E6 , How To Fix

written by Jamila | 8 September 2018

The error E6 comes from the engine, it is the electronic engine card if it is an inverter range.

Communication error E6 Between Outside and inside

www.mbsm.pro, FN66Q14G ,Refrigerator Compressors, equivalent in 1/5 HP ,R12, Powerful

written by Lilianne | 8 September 2018



www.mbsm.pro, FN66Q14G ,Refrigerator Compressors, equivalent
in 1/5 HP ,R12, Powerful

**www.mbsm.pro, COMPRESSOR ,
1/5Hp ,EGL75AA , R134A, 155W,
LBP, 7.39CM3**

written by Lilianne | 8 September 2018

Low-temperature refrigerator compressor with a cylinder capacity of 7.39cm³ and a cooling capacity of 155W. Works with refrigerant R134a.

**www.mbsm.pro, Compresseur
THG1365YGS, R134a ,1/5HP
,230V ,148W**

written by Jamila | 8 September 2018

Gamme: Froid Commercial / Industriel

Type de machine: Divers

Type de produit: Compresseur

Sous-type de produit: Compresseur

Marque: Tecumseh

Original

www.mbsm.pro, Branchement Unité extérieure , LG ,Media , Général , Samsung, Haier , Galanze ,Gree ,Maxwelle, Vestel

written by Jamila | 8 September 2018

Branchement Unité extérieure , LG ,Media , Général , Samsung,
Haier , Galanze ,Gree ,Maxwelle, Vestel

www.mbsm.pro ,Panasonic , Tested OK ,Refrigeration Compressors ,Industrial Devices

written by Jamila | 8 September 2018

Panasonic is known throughout the world for manufacturing high quality, reliable products. Our line of refrigeration compressors continues this tradition. Panasonic provides premium compressors for refrigerator manufacturers all over the world. Our compressors are recognized for superior construction, low noise, and most of all reliable performance. From our high efficiency inverter drive compressors to our

high capacity QA series, our complete line of compressors are designed to meet the needs for nearly all refrigeration applications.

www.mbsm.pro , Major Cara, climatiseurs , Code Erreur EC , Solution Tester

written by Jamila | 8 September 2018

Les codes erreurs donnent une approche du type de dysfonctionnement. Faire appel à un professionnel pour les interpréter.

Un code peut provenir de plusieurs causes différentes.

Un dysfonctionnement peut être indiqué par plusieurs codes erreurs

www.mbsm.pro, Electrolux GL75AA Refrigerator 1/5 HP, Compressor Cooling solution for Refrigerators

written by Jamila | 8 September 2018



Picture5 Mbsm Dot Pro : www.mbsm.pro

www.mbsm.pro, Electrolux GL75AA Refrigerator 1/5 HP, Compressor Cooling solution for Refrigerators

www.mbsm.pro , LG MA42LBJG Refrigerator Compressor 1/6 Hp , Cooling solution for Refrigerators

written by Jamila | 8 September 2018



www.mbsm.pro

Cooling solution for Refrigerators & Commercial Appliances
This M-series reciprocating LBP compressor provides complete cooling solution for Domestic & Commercial refrigeration appliances. Compact Size, Silent operation, Low Voltage start ability (LVS) are its prominent features. M-Series compressor caters to 6s quality assurance and has globally proven reliability.

www.mbsm.pro , Embraco FG 75 HAK ,true cooler compressor, 1/4hp

written by Lilianne | 8 September 2018



FG 85 HAK,
FG 75 HAK,
FFU 80 HAK ,
FFU 100 HAK,
FG 65 HAK ,
EMYE 70 HEP,
EMT 60 HLP,
EMT 49 HLP ,
EMIE 65 HER ,
EMIE 40 HJP,
EMI 70 HER ,
EM 55 HNR ,
EM 45 HNR ,
EM 30 HHR ,
EGAS 100 HLR ,
EGAS 90 HLR ,
EGAS 80 HLR ,



PictureS Mbsm Dot Pro : www.mbsm.pro

FG 85 HAK

FG 75 HAK

FFU 80 HAK

FFU 100 HAK

FG 65 HAK

EMYE 70 HEP

EMT 60 HLP

EMT 49 HLP

EMIE 65 HER

EMIE 40 HJP

EMI 70 HER

EM 55 HNR

EM 45 HNR

EM 30 HHR

EGAS 100 HLR

EGAS 90 HLR

EGAS 80 HLR

PictureS Mbsm Dot Pro : www.mbsm.pro

