

**Mbsm.pro, Freeser, Ariston, ECH240s1, 240 L, Compressor, TECUMSEH BRASIL, THb1355y, 1/5 hp, LBP, R134A, 100g, replaced by, egm70af, gl70aa, capillarie 0.026, 1.2 m, Alert -10**

written by Lilianne | 7 May 2022



REDMI NOTE 9  
WWW.MBSM.PRO IMAGE

2022/5/6 01:50

Private Picture Copyright: WWW.MBSM.PRO

Mbsm.pro, Freeser, Ariston, ECH240s1, 240 L, Compressor, TECUMSEH BRASIL, THb1355y, 1/5 hp, LBP, R134A, 100g, replaced by, egm70af, gl70aa, capillarie 0.026, 1.2 m, Alert -10

---

**Mbsm.pro, Compressor Necchi,  
Esm5, 1/5 Hp, R12, Replaced  
by , COMPRESSOR, DANFOSS,TL  
5G, 1/6++ (1/5 hp) HP, MBP /  
HBP -R134a,  
220-240V/1/50/60Hz,  
displacement 5.08 cm<sup>3</sup>, motor  
type RSCR**

written by Lilianne | 7 May 2022

Mbsm.pro, Compressor Necchi, Esm5, 1/5 Hp, R12, Replaced by ,  
COMPRESSOR, DANFOSS,TL 5G, 1/6++ (1/5 hp) HP, MBP / HBP -  
R134a, 220-240V/1/50/60Hz, displacement 5.08 cm<sup>3</sup>, motor type  
RSCR

---

**Mbsm.pro, Compressor,  
AZ1339Y, 134a, Replaced by,  
THB1340Y, 1/8 Hp, PTCSIR, Lbp**

written by Lilianne | 7 May 2022



Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

UH0120006 THB1335Y 1/12 3,58 250 C 41 58 81 109 142 181 PTCSIR  
220/1/50 84,7 0,53 7,25  
UH0120041 THB1340Y 1/10 4,23 250 C 49 72 99 132 170 213 PTCSIR  
220/1/50 93 0,59 9  
UH0120076 THB1350Y 1/8 5,6 250 C 56 83 118 162 214 275 PTCSIR  
220/1/50 108 0,71 9  
UH0120111 THB1360Y 1/6 6,1 250 C 76 105 141 185 238 300 PTCSIR  
220/1/50 129 0,88 11  
UH0120146 AZ1320Y 1/15 2,95 270 C 19 32 48 69 95 125 PTCSIR

220/1/50 67,3 0,47 7,3  
 UH0120181 AZ1330Y 1/12 3,6 270 C 34 51 73 99 130 166 PTCSIR  
 220/1/50 81,7 0,51 6,9  
 UH0120216 AZ1335Y 1/10 4 250 C 41 58 81 109 142 181 PTCSIR  
 220/1/50 87,2 0,56 10  
 UH0120251 AZ1339Y 1/8 5 270 C 45 69 99 135 178 228 PTCSIR  
 220/1/50 102 0,72 10  
 UH0120286 AZ1348Y 1/6 5,6 250 C 59 83 116 158 209 271 PTCSIR  
 220/1/50 123 0,87 11  
 UH0120321 AZ1355Y 1/6 5,9 300 C 70 101 141 189 246 312 PTCSIR  
 220/1/50 127 0,87 11  
 UH0120356 AEZ1370Y 1/5 8,1 450 C 98 133 180 239 311 397 PTCSIR  
 220/1/50 172 1,19 11  
 UH0120391 AEZ1365Y 1/5 8,9 450 C 85 129 185 254 335 430 PTCSIR  
 220/1/50 181 1,20 10

## Highlights Fagor Compressor Az1339y-f R134a

Modèles Models	R-	Remplacé par Superseded by	R-	Remplacé par Superseded by	R-	Remplacé par Superseded by	R-
P1218	12	AE14Z6	12	AZ1320/AD	12	AZ1320Y	134a
P/SP1219	12	AM12Z7	12	AE12W	12	AE12Z7	12
AZ1335Y	134a	THB1335Y	134a				
AZ1339Y	134a	THB1340Y	134a				
P/SP91	12	AE8ZA7	12	AEZ1336A	12	AZ1335A/D	12
AE65ZD7	12	XXXXXX		XXXXXX		AZ1348Y	134a

UH0120006	THB1335Y	1/12	3,58	250	C		41	58	81	109	142	181		PTCSIR	220/1/50	84,7	0,53	7,25
UH0120041	THB1340Y	1/10	4,23	250	C		49	72	99	132	170	213		PTCSIR	220/1/50	93	0,59	9
UH0120076	THB1350Y	1/8	5,6	250	C		56	83	118	162	214	275		PTCSIR	220/1/50	108	0,71	9
UH0120111	THB1360Y	1/6	6,1	250	C		76	105	141	185	238	300		PTCSIR	220/1/50	129	0,88	11
UH0120146	AZ1320Y	1/15	2,95	270	C		19	32	48	69	95	125		PTCSIR	220/1/50	67,3	0,47	7,3
UH0120181	AZ1330Y	1/12	3,6	270	C		34	51	73	99	130	166		PTCSIR	220/1/50	81,7	0,51	6,9
UH0120216	AZ1335Y	1/10	4	250	C		41	58	81	109	142	181		PTCSIR	220/1/50	87,2	0,56	10
UH0120251	AZ1339Y	1/8	5	270	C		45	69	99	135	178	228		PTCSIR	220/1/50	102	0,72	10
UH0120286	AZ1348Y	1/6	5,6	250	C		59	83	116	158	209	271		PTCSIR	220/1/50	123	0,87	11
UH0120321	AZ1355Y	1/6	5,9	300	C		70	101	141	189	246	312		PTCSIR	220/1/50	127	0,87	11
UH0120356	AEZ1370Y	1/5	8,1	450	C		98	133	180	239	311	397		PTCSIR	220/1/50	172	1,19	11
UH0120391	AEZ1365Y	1/5	8,9	450	C		85	129	185	254	335	430		PTCSIR	220/1/50	181	1,20	10
UH0120426	AEZ1380Y	1/4	9,4	450	C									RSIR	220/1/50	232	1,85	10
UH0120461	AEZ2380Y	1/4	9,4	450	C/V		112	167	228	297	373	457		CSIR	220/1/50	227	1,78	12
UH0120496	AE1410Y	1/4	12,05	450	C									RSIR	220/1/50	239	1,83	14
UH0120531	CAE2410Y	1/4	12,05	450	C/V		110	175	258	360	481	623		CSIR	220/1/50	239	1,76	11
UH0120566	AE1412Y	1/3	14,15	450	C									RSIR	220/1/50	273	1,82	14
UH0120601	CAE2412Y	1/3	14,15	450	C/V		115	201	304	426	567	728		CSIR	220/1/50	289	1,96	13
UH0120636	CAE2414Y	1/3	16	450	C/V		121	188	275	382	515	676		CSIR	220/1/50	334	2,20	17



Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbsm\_dot\_pro\_private\_PDF\_THB1340Y-Tecumseh-do-BrazilTélécharger

Mbsm\_dot\_pro\_private\_PDF\_Coldco-Fridgecare-Tecumseh-2017Télécharger

Mbsm\_dot\_pro\_private\_PDF\_az1339y1Télécharger

Mbsm\_dot\_pro\_private\_PDF\_az1339yTélécharger

Please check that this part is compatible with your device model. Our customer service can advise you.

Appliance models affected:

- CB1290SI – CB1290SIH (BRANDT),
- CB195 – CB195H (BRANDT),
- CC1950 – CC1950J (BRANDT),
- CCSI1290 – CCSI1290J (BRANDT),
- CFG24N – CFG24NG (FAGOR),
- CFH24 – CFH24J (FAGOR),
- CFH24 / 1 – CFH24 / 1J (FAGOR),
- CFS15 – CFS15J (FAGOR),
- CFSA15 – CFSA15G (FAGOR),
- DUN1912B – DUN1912BA (BRANDT),
- DUN1917B – DUN1917BA (BRANDT),
- DUN2412B – DUN2412BA (BRANDT),
- DUN99B – DUN99BA (BRANDT),
- DU03666 – DU03666A (BRANDT),
- DU03676 – DU03676A (BRANDT),
- RB315 – RB315A (BRANDT),
- RB316 – RB316A (BRANDT),
- RB348 – RB348A (BRANDT),
- RB349 – RB349A (BRANDT),
- RBM355 – RBM355A (BRANDT),
- RBM356 – RBM356A (BRANDT),
- RS2180 – RS2180A (BRANDT),
- RS2180C – RS2180CA (BRANDT),
- RS6287 – RS6287A (BRANDT),
- RS6310 – RS6310A (BRANDT),
- SFB310KIT – SFB310KITA (BURNING).