

LOW BACK PRESSURE ,HITACHI ,  
Compressor FL1257-SR , 1/5HP , R134a  
,135 W , BTU/Hr 512 ,Curcuit RSIR

Category: Solutions,Tester ok  
written by Lilianne | 23 April 2020

HITACHI FL1257-SD

220-240V 50Hz OIL 2006.05.13



SERIAL NO.09760 HFC-134a



WARNING HIGH TEMPERATURE  
ELECTRIC SHOCK

K12

DO NOT TOUCH



SHOT ON M6T  
MEIZU