

# Mbsm.pro, Compressor, Qd59, 1/6 hp++, 1/5 hp-, 142 w, QD series Compressor

written by Lilianne | 27 March 2023



Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbsm.pro, Compressor, Qd59, 1/6 hp++, 1/5 hp-, 142 w, QD series Compressor

---

# Board for the White Point refrigerator

written by Lilianne | 27 March 2023



Board for the White Point refrigerator

---

**Mbsm.pro, Fridge Compressor,  
Tecumseh, AZ Freezer, AE,  
R134a, AE4460YFZ1C, ae8284br,  
ae4460y, ae 8284 br, ae 4460  
y, 1/2 hp, hbp**

written by Lilianne | 27 March 2023



Tecumseh

(P)



AE-8284-BR


R-134a

AE4460Y-FZ1C

220-240V ~ 50 Hz

LRA: 18.0

525-10017



(T)



51

K2617

23 020341



THERMALLY PROTECTED  
COUNTRY OF ORIGIN: BRAZIL

SUCTION



Galaxy M32

Mbsm.pro, Fridge Compressor, Tecumseh, AZ Freezer, AE, R134a, AE4460YFZ1C, ae8284br, ae4460y, ae 8284 br, ae 4460 y, 1/2 hp, hbp

---

# Mbsm.pro, Kikr inverter, kikdr G08b05

written by Lilianne | 27 March 2023



Mbsm.pro, Kikr inverter, kikdr G08b05

---

# رموز أعطال , غسالة , Mbsm.pro Hoover , هوفر

written by mahdi miled | 27 March 2023

رموز أعطال غسالة هوفر  	
سبب العطل	الرمز
تنبيه سينسور الحرارة / سينسور المجفف	<b>E13</b>
أفحص السخان / الكارته	<b>E14</b>
عطل في كارته التحكم	<b>E15</b>
افحص السخان / توصيلاته	<b>E16</b>
أفحص التاكو وتوصيلاته	<b>E17</b>
أفحص كارته الغسالة	<b>E18</b>

Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbsm.pro , رموز أعطال , غسالة هوفر , Hoover

# Mbsm.pro, compressor, Embraco, Aspera, 1/3 hp++, 1/2 hp-, emt2130GK

written by Lilianne | 27 March 2023



Mbsm.pro, compressor, Embraco, Aspera, 1/3 hp++, 1/2 hp-, emt2130GK

# Mbsm.pro, Compressor, 1/8 hp, BP5125Z, TL3G, EM30HNP, PW3.5HK9, AZ4410Y, GD30PB/MB, az3410

written by Lilianne | 27 March 2023





Samsung Dual Camera

تم الالتقاط بواسطة  
الخاص بي Galaxy A30

Mbsm.pro, Compressor, 1/8 hp, BP5125Z, TL3G, EM30HNP,  
PW3.5HK9, AZ4410Y, GD30PB/MB, az3410

---

## **Mbsm.pro, Files, Pdf, Compressor, HPY16AAa, 1/4 hp, Danfos**

written by rober us | 27 March 2023



- Compresseur hermétique Cubigel – Huayi Modèle HPY16AAA (LBP) R600 220-240V 50Hz 1/4HP Projection 6.5" / 3(S) Capillaire d'expansion  $-35\frac{1}{4}C$   $-10\frac{1}{4}C$
- Mbsm\_dot\_pro\_private\_PDF\_danfoss\_HPY16AAa\_R600a\_220\_50



---

## **Mbsm.pro, compressor, Tecumseh, R22, AEZ3440E, 1/3hp-, 1/4 hp++**

written by Lilianne | 27 March 2023



2023/3/15 16:15

Mbsm.pro, compressor, Tecumseh, R22, AEZ3440E, 1/3hp-, 1/4 hp++

---

# Mbsm.pro, Tachymetre ,Lave, linge , LG

written by Lilianne | 27 March 2023



Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbsm.pro, Tachymetre ,Lave, linge , LG