

TFS4AT, 102u 2081, 102u2081, 1/12 hp, r12, Lbp, 80 w / -25 °C, -10/-40 °C, Danfoss, r12, r22, r502, Compressor, PDF

written by Amina | 30 October 2023



TFS4AT, 102u 2081, 102u2081, 1/12 hp, r12, Lbp, 80 w / -25 °C,
-10/-40 °C, Danfoss, r12, r22, r502, Compressor, PDF

**Original, R600A, Jiaxipera,
Fridge, compressor, T1114Y,
1/5 hp, 168 W, lbp, 9.6 cm³**

written by Amina | 30 October 2023

jiaxipera®

CCC

CE

Warning Risk of fire / flammable materials
JIAXIPERA COMPRESSOR CO., LTD

R600a

TG1114Y

IVA

220-240V-50Hz

AL

SUCTION

TG1114YP112905843

Original, R600A, Jiaxipera, Fridge, compressor, T1114Y, 1/5
hp, 168 W, lbp

**Compressor, TLS4FT, SECOP,
102G4424, 102G 4424, DANFOSS,
1/8 hp++, 98 w, lbp, r134**

written by Amina | 30 October 2023



Private Picture Copyright : WWW.MBSM.PRO

Compressor, TLS4FT, SECOP, 102G4424, 102G 4424, DANFOSS, 1/8 hp++, 98 w, lbp, r134

Compressor, Samsung, MSA182Q-L2H, 1/3 hp, Lbp, 264 Kcal, 307 W, 1048 Btu, r134a, refrigerator, RT72SBPN, 1.3 A, 554 L, 2 Doors

written by Amina | 30 October 2023



Private Picture Copyright : WWW.MBSM.PRO

Compressor, Samsung, MSA182Q-L2H, 1/3 hp, Lbp, 264 Kcal, 307 W, 1048 Btu, r134a, refrigerator, RT72SBPN, 1.3 A, 554 L, 2 Doors

**Commercial refrigerator,
compressors, GLY16RG, 3/8
hp++, R134a, HMBP, 1492W,
r134, Compressor ACC,
Cubigel, Huayi, Electrolux,
ZEM**

written by Amina | 30 October 2023



Commercial refrigerator, compressors, GLY16RG, 3/8 hp++, R134a, HMBP, 1492W, r134, Compressor ACC, Cubigel, Huayi, Electrolux, ZEM

**Compressor, hermetic, piston,
Embraco, NEK6214U, 1/2 hp++,
hbp, R290, 12,12 cm³**

written by Amina | 30 October 2023



Private Picture Copyright : WWW.MBSM.PRO

Compressor, hermetic, piston, Embraco, NEK6214U, 1/2 hp++,
hbp, R290, 12,12 cm³

PANASONIC, A/C, Compressor,

2KS324D5LA04, 18000 BTU, r22, 1.5 ton, K Series

written by Amina | 30 October 2023



PANASONIC, A/C, Compressor, 2KS324D5LA04, 18000 BTU, r22, 1.5 ton, K Series

RT 1320 windsor, windsor refrigerator, 13.2 Feet/cub, 400 L, Compressor, Embraco, ecu75hlp, 250 w, 1/4 hp, Lbp, r134, 180 g, 7.5 cm³, 220-240 V at 50 Hz

written by Amina | 30 October 2023



RT 1320 windsor, windsor refrigerator, 13.2 Feet/cub, 400 L,
Compressor, Embraco, ecu75hlp, 250 w, 1/4 hp, Lbp, r134, 180
g, 7.5 cm³, 220-240 V at 50 Hz

**Tecumseh, AEZ1410D,
compressor, 1/3 HP, r12**

written by Amina | 30 October 2023



R12 LRA 4.6

208-220V ~ 50Hz RLA 1.8

6A36490300
AEZ1410D

52 D1405 10 143826 A

CE

COUNTRY OF ORIGIN: FRANCE THERMALLY PROTECTED

WARNING

To avoid burns,
IMMEDIATELY GET AWAY
if you hear sizzling,
clicking or popping inside
the compressor.
Improper servicing can lead
to electrocution, fire or
explosion. Service only by
trained professional.

ADVERTENCIA

Para evitar quemaduras,
RETIRESE INMEDIATAMENTE
al oír chisporroteos, siseos o
estallidos dentro del compresor.
El mantenimiento inadecuado
puede causar electrocución,
incendio o explosión. Solamente
profesionales entrenados
pueden hacer los servicios de
mantenimientos.


AVERTISSEMENT

Pour vous prévenir de brûlures,
ELOIGNEZ VOUS IMMEDIATEMENT
si vous entendez des grésaillements,
crépitements ou petites explosions à
l'intérieur du compresseur.
Une maintenance inappropriée
peut engendrer un incendie, une
électrocution ou une explosion.
Toute intervention est réservée à
un professionnel habilité.

Tecumseh, AEZ1410D, compressor, 1/3 HP, r12

Compressor, LG, QP407PMA, 2.5 hp, r22, 24045 btu, 7048 w

written by Amina | 30 October 2023



Private Picture Copyright : WWW.MBSM.PRO

Compressor, LG, QP407PMA, 2.5 hp, r22, 24045 btu, 7048 w