

# Mbsm.pro, LG, SPLITROOM, AIR CONDITIONER, BMPU19K, 19000 btu, r410, 1400 g

written by Lilianne | 2 September 2022



Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbsm.pro, LG, SPLITROOM, AIR CONDITIONER, BMPU19K, 18000 btu

---

**Mbm.pro, Compressor,  
UR8b180DTAeH, Samsung ,  
R22,18000 btu, 8 A**

written by Lilianne | 2 September 2022



Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbm.pro, Compressor, UR8b180DTAeH, Samsung , R22,18000 btu

---

**Mbsm.pro, Daewoo Compressor,  
YX58LHP5, R134a, 200 w, 1/4  
hp, 683 BTU, Lbp, 95 G,  
Congélateur, CONDOR NOFROST,**

# 375L

written by Lilianne | 2 September 2022

	JX58LHK4	5.84	161	170	198	675	1.06	1.23	4.19	CSIR	ST/FC	8.2	230
	JX58LHP4	5.84	139	170	198	675	1.22	1.42	4.85	RSCR	ST/FC	8.2	230
	JX58LHP4-K	5.85	155	170	198	675	1.10	1.28	4.35	RSCR	ST/FC	8.2	230
	JX58LHS4	5.84	150	170	198	675	1.13	1.32	4.50	RSIR	ST/FC	8.2	230
YH	HPL15YH-4	5.12	122	135	157	536	1.11	1.29	4.39	RSCR	ST/OC/FC	8.9	290
	HPL17YH-4	5.55	131	148	172	587	1.13	1.31	4.48	RSCR	ST/OC/FC	8.9	290
	HPL19YH-4	5.84	137	170	198	675	1.24	1.44	4.92	RSCR	ST/OC/FC	9.5	290
	HDL21YH-4	6.72	156	189	220	750	1.21	1.41	4.81	CSIR	ST/OC/FC	9.5	290
	HPL21YH-4	6.73	155	188	219	746	1.21	1.41	4.81	RSCR	ST/OC/FC	9.5	290
	HPL23YH-4	7.03	165	201	234	798	1.22	1.42	4.83	RSCR	ST/OC/FC	9.5	290
	HPL26YH-4	8.25	205	235	273	933	1.15	1.33	4.55	RSCR	ST/OC/FC	9.5	290
YX	YX46LHP4	4.62	104	125	145	496	1.20	1.40	4.77	RSCR	ST/OC/FC	8.8	290
	YX51LHP4	5.12	120	150	174	595	1.25	1.45	4.96	RSCR	ST/OC/FC	8.8	290
	YX51LHP4-K	5.12	128	144	168	572	1.12	1.31	4.46	RSCR	ST/OC/FC	8.8	290
	YX58LHP4	5.84	133	172	200	683	1.29	1.50	5.13	RSCR	ST/OC/FC	9.8	290
YG	HPL21YG-4	6.73	175	185	215	734	1.06	1.23	4.20	RSCR	ST/OC/FC	9.0	290
	HPL27YG-4A	8.69	232	250	291	992	1.08	1.25	4.28	RSCR	ST/OC/FC	9.5	290
	HPL30YG-4	9.92	247	283	329	1123	1.15	1.33	4.55	RSCR	ST/OC/FC	9.5	290

Private Picture Copyright : WWW.MBSM.PRO



Private Picture Copyright : WWW.MBSM.PRO





Mbsm\_dot\_pro\_private\_PDF\_YX58LHP5-R134aTélécharger

---

**Mbsm.pro, Hermetic  
compressor, Aspera, Embraco,  
NEK6212Z, R134a, 1/2 hp , HBP**

written by Lilianne | 2 September 2022



Mbsm.pro, Hermetic compressor, Aspera, Embraco, NEK6212Z,  
R134a, 1/2 hp , HBP

---

**Mbsm.pro, R600a, Aruki  
Compressors, Compressor,  
QD65Y(N) (1/9HP) , QD75Y(J)  
(1/8+HP), QD85Y(J) (1/7+HP),  
QD91Y(J) (1/6HP), QD103Y(J)  
(1/6+HP)**

written by Lilianne | 2 September 2022



 **QD103Y**  
220-240V~50Hz 1PH

     R600a

  **NO. 15592401** Warning: Risk of fire

Hangzhou Qianjiang Refrigeration Group Co.,Ltd

Mbsm.pro, R600a, Aruki Compressors, Compressor, QD65Y(N)  
(1/9HP) , QD75Y(J) (1/8+HP), QD85Y(J) (1/7+HP), QD91Y(J)  
(1/6HP), QD103Y(J) (1/6+HP)

---

**Mbsm.pro, compressor,  
MT160HW4D , 13 hp, MT160,  
Displacement: 271.55cm<sup>3</sup>/rev**

written by Lilianne | 2 September 2022

*Mbsm.pro, Danfoss, Compressor, MT100HS4D, 8.3HP, R22, 380V,  
3PH*



---

**Mbsm.pro, Compressor, T3, 3.3  
hp, 30000 btu, nht52vbat, 14  
A, Mitsubishi Compressor,  
r22, 4.5 bar**

written by Lilianne | 2 September 2022



Mbsm.pro, Compressor, T3, 3.3 hp, 30000 btu, nht52vbat, 14 A,  
Mitsubishi Compressor

---

**Mbsm.pro, Embraco, Aspera,  
NEK2150CK, 1/2 hp, freezing  
(LBP), 121 cm<sup>3</sup>, R404A /RS07A  
/ R452A**

written by Lilianne | 2 September 2022





 **Embraco Accera** **NEK2130GK**  


THERMALLY PROTECTED		220 - 240V ~ 50Hz
	R 404A	
POE. OIL 350CC	1 PH	


**MADE IN SLOVAKIA** **NO START WITHOUT STARTING DEVICE**  
  
 958BA51      FX      N10ESUX1

  
**R 404A**

Mbsm.pro, Embraco, Aspera, NEK2150CK, 1/2 hp, freezing (LBP),  
121 cm<sup>3</sup>, R404A /RS07A / R452A

---

## **Mbsm.pro, Raccord femelle 15 a souder cuivre 14, plomberie**

written by Lilianne | 2 September 2022

Mbsm.pro, Raccord femelle a souder cuivre 14



---

## **Mbsm.pro, Compressor, Mly12LA, 1/3 hp-, Lbp , 404a, Low Back Pressure R404a/R507 compressors Cubigel – Spain**

written by Lilianne | 2 September 2022

Mbsm.pro, Compressor, Mly12LA, 1/3 hp-, Lbp , 404a