

**Mbsm.pro, Fridge Compressor,
Tecumseh, AZ Freezer, AE,
R134a, AE4460YFZ1C, ae8284br,
ae4460y, ae 8284 br, ae 4460
y, 1/2 hp, hbp**

written by Lilianne | 27 March 2023



(P)



Tecumseh

AE-8284-BR


R-134a

AE4460Y-FZ1C

220-240V ~ 50 Hz

LRA: 18.0

525-10017



(T)



51

K2617

23 020341



THERMALLY PROTECTED
COUNTRY OF ORIGIN: BRAZIL

SUCTION



Galaxy M32

Mbsm.pro, Fridge Compressor, Tecumseh, AZ Freezer, AE, R134a, AE4460YFZ1C, ae8284br, ae4460y, ae 8284 br, ae 4460 y, 1/2 hp, hbp

Mbsm.pro, Kikr inverter, kikdr G08b05

written by Lilianne | 27 March 2023



Mbsm.pro, Kikr inverter, kikdr G08b05

رموز أعطال , غسالة , Mbsm.pro , هوفر , Hoover

written by mahdi miled | 27 March 2023

رموز أعطال غسالة هوفر  	
سبب العطل	الرمز
تنبيه سينسور الحرارة / سينسور المجفف	E13
أفحص السخان / الكارته	E14
عطل في كارته التحكم	E15
افحص السخان / توصيلاته	E16
أفحص التاكو وتوصيلاته	E17
أفحص كارته الغسالة	E18

Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro , رموز أعطال , غسالة هوفر , Hoover

Mbsm.pro, compressor, Embraco, Aspera, 1/3 hp++, 1/2 hp-, emt2130GK

written by Lilianne | 27 March 2023



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, compressor, Embraco, Aspera, 1/3 hp++, 1/2 hp-, emt2130GK

Mbsm.pro, Compressor, 1/8 hp, BP5125Z, TL3G, EM30HNP, PW3.5HK9, AZ4410Y, GD30PB/MB, az3410

written by Lilianne | 27 March 2023



Samsung Dual Camera

تم الالتقاط بواسطة
الخاص بي Galaxy A30

Mbsm.pro, Compressor, 1/8 hp, BP5125Z, TL3G, EM30HNP, PW3.5HK9, AZ4410Y, GD30PB/MB, az3410

Mbsm.pro, Files, Pdf, Compressor, HPY16AAa, 1/4 hp, Danfos

written by rober us | 27 March 2023



Private Picture Copyright : WWW.MBSM.PRO


- Compresseur hermétique Cubigel – Huayi Modèle HPY16AAA (LBP) R600 220-240V 50Hz 1/4HP Projection 6.5" / 3(S) Capillaire d'expansion $-35\frac{1}{4}C$ $-10\frac{1}{4}C$
- Mbsm_dot_pro_private_PDF_danfoss_HPY16AAa_R600a_220_50



Private Picture Copyright : WWW.MBSM.PRO

**Mbsm.pro, compressor,
Tecumseh, R22, AEZ3440E,
1/3hp-, 1/4 hp++**

written by Lilianne | 27 March 2023



2023/3/15 16:15

Mbsm.pro, compressor, Tecumseh, R22, AEZ3440E, 1/3hp-, 1/4 hp++

Mbsm.pro, Tachymetre ,Lave, linge , LG

written by Lilianne | 27 March 2023



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Tachymetre ,Lave, linge , LG

Gr-ef31

written by Lilianne | 27 March 2023



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Toshiba, no frost, refrigerator, Gr-ef31

**Mbsm.pro, Compressor,
ELECTROLUX, ACC, GL60AA,
GVY57AA, 1/6 hp, r134**

written by Jamila | 27 March 2023



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Compressor, ELECTROLUX, ACC, GL60AA, GUY57AA, 1/5 hp, r134