

**Mbsm.pro, compressor, Sanyo,
Rotary, Split system air
conditioner, Compressors, C-
R221H5S, S6231526791, 24000
btu, R22, 3 hp, 2 ton**

written by Lilianne | 22 January 2024

SANYO



MODEL C-R221H5S

CODE 80687145



CHINA RESOURCES SANYO (SHENYANG) COMPRESSOR CO., LTD.
沈阳三洋压缩机有限公司

WARNING-SERVICEMAN

- 1. FIELD SERVICE LEAK TEST PRESSURE MUST NOT EXCEED 40PSI (2.7MPa)
 - 2. THIS COMPRESSOR MUST BE GROUNDED.
 - 3. DO NOT OPERATE WITHOUT PROTECTIVE COVER OVER TERMINALS
- DISCONNECT ALL POWER BEFORE REMOVING THE PROTECTIVE COVER

CAUTION

COMPRESSOR HOUSING MAY REACH 150°C WITH INTERNAL HEATDUECTOR
APPROVED BY SANYO AND TESTED IN ACCORDANCE WITH EN 1254

Mbsm.pro, compressor, Sanyo, Rotary, Split system air conditioner, Compressors, C-R221H5S, S6231526791, 24000 btu,

R22, 3 hp, 2 ton