

# Mbsm.pro, AJ5515E-FZ3C, AJ5515E, AJ5EL1GF602 , Tecumseh, 1-1/4 hp, R22, Tecumseh compressor, Hermetic piston

written by Lilianne | 26 June 2024



Mbsm.pro, AJ5515E-FZ3C, AJ5515E, AJ5EL1GF602 , Tecumseh, 1-1/4  
hp, R22, Tecumseh compressor, Hermetic piston

---

# Mbsm.pro, Compressor, TYA4475YKS, Tecumseh, TYA 4475 YKS, TY302-KS-116, 3/4 hp, hbp, r134

written by Lilianne | 26 June 2024



Mbsm.pro, Compressor, TYA4475YKS, Tecumseh, TYA 4475 YKS,  
TY302-KS-116, 3/4 hp, hbp, r134

---

**Mbsm.pro, Compressor,  
THB1360YNS, Tecumseh, hermeti  
c compressor, Thb1360y,  
R-134a, 1/5 hp, 230v, lbp**

written by Lilianne | 26 June 2024



Mbsm.pro, Compressor, THB1360YNS, Tecumseh, hermetic  
compressor, Thb1360y, R-134a, 1/5 hp, 230v, lbp



---

**Mbsm.pro, Compressor , Air  
Conditioning, r22, Tecumseh,  
AGC5568EXG, AG144UT-001-J7,  
5-1/2 HP, 4 ton, R-22, 56700  
btu, HBP/AC, 460V 3ph 60Hz  
380-420V**

written by Lilianne | 26 June 2024



Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbsm.pro, Compressor , Air Conditioning, r22, Tecumseh,  
AGC5568EXG, AG144UT-001-J7, 5-1/2 HP, 4 ton, R-22, 56700 btu,  
HBP/AC

---

**Mbsm.pro, Compressor,  
Tecumseh, 1/2 hp, CAE9470Z,  
(POE), HBP, R404A,  
220-240V/1/50Hz , replaced by  
AE4470Z**

written by Lilianne | 26 June 2024



Tecumseh

(P)



6B89090200

CAE9470Z

200-220V

R404A

WHOLESALE

LFA-22



53 B2514 10 073413 A

COUNTRY OF ORIGIN: FRANCE

THERMALLY PROTECTED

625-100178





Mbsm.pro, Compressor, Tecumseh, 1/2 hp, CAE9470Z, (P0E), HBP, R404A, 220-240V/1/50Hz , replaced by AE4470Z

---

**Mbsm.pro, Tecumseh, 1/2 hp,  
HBP, Caj4461y, Caj4461A,  
Tecumseh, Compressor,  
Refrigeration, R410A,  
CAJ9510T-F1, 1hp, hbp**

written by Lilianne | 26 June 2024




Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)


Mbsm.pro, Tecumseh, 1/2 hp, HBP, Caj4461y, Caj4461A, Tecumseh, Compressor, Refrigeration, R410A, CAJ9510T-F1, 1hp, hbp

# Mbsm.pro, COMPRESOR, TECUMSEH, BRASIL, 1/5 HP, TW1368YS, R-134, 1bp

written by Lilianne | 26 June 2024



HP	Compresor	ERR Btu/Wh
1/8	THG1340YS	4,25
1/6	THG1352YS	4,40
1/5	THG1358YS	4,41
1/5+	TW1368YS	4,26
	TSA1374YS	4,90
1/4	TW1380YS	4,45
	TSA1380YS	5,10
	TPH1380YS	5,00



Mbsm.pro, COMPRESOR, TECUMSEH, BRASIL, 1/5 HP, TW1368YS, R-134, 1bp



---

**Mbsm.pro, COMPRESSOR,  
TECUMSEH, AEA4440YES,  
AE4440YS, AE630, 1/3+ HP,  
220V, 1ph, R134, hbp**

written by Lilianne | 26 June 2024



Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbsm.pro, COMPRESSOR, TECUMSEH, AEA4440YES, AE4440YS, AE630, 1/3+ HP, 220V, 1ph, R134, hbp

---

# Mbsm.pro, COMPRESSOR, TECUMSEH, 1/3 hp , TP1413YS, R-134A, 220V, 1bp

written by Lilianne | 26 June 2024



Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbsm.pro, COMPRESSOR, TECUMSEH, 1/3 hp , TP1413YS, R-134A,  
220V, 1bp

---

# Mbsm.pro, Tecumseh, Compressor, 1HP, R404 ,MHBP, CAJ9510Z, r22

written by Lilianne | 26 June 2024





Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbsm.pro, Tecumseh, Compressor, 1HP, R404 ,MHBP, CAJ9510Z, r22